




# SUPPLEMENTARY MANUAL

for SH-U01

CUT THE GRAY/RED WIRE BEHIND THE INSTRUMENT CLUSTER.


CONNECT THE SH GREEN WIRE TO THE GRAY/RED WIRE END AT THE SPEEDOMETER SIDE.

CONNECT THE SH WHITE WIRE TO THE GRAY/RED WIRE END AT THE WIRING HARNESS SIDE.



CONNECT THE SH BLACK WIRE TO CHASSIS GROUND.

CONNECT THE SH RED WIRE TO A SWITCHED +12V POWER LEAD.



SPEEDOMETER IS IN SYNC WITH GPS AFTER CALIBRATION.

